

Royalwood Golf & RV Resort, Drinking Water System Annual Report for 2022

- This report covers from Jan. 01 2022 to Dec. 31 2022
- The owners are Ehrenholz Estates, Manager Dan Ehrenholz, Phone 604-823-4653 Ext.4
- The system operator is Dan Ehrenholz (operator cert. # 4678)
- A summary of the “Bacteriological Water Analysis” is attached.
- A summary of the arsenic monitoring test reports are attached
- A summary of the system operations (work done & improvements planned) are attached

Royalwood uses both the Ultraviolet Light and Chlorine to disinfect the drinking water.

*Anytime the water in a particular faucet has not been used for 6 hours or longer, flush the cold water pipes by running the water until you notice a change in temperature. (This could take as little as 5 to 30 seconds if there has been recent heavy water use such as showering or toilet flushing. Otherwise it could take two minutes or longer.) The more time water has been sitting in the pipes the more lead it may contain. **Royalwood’s system is a newer system and uses plastic pipes, but your RV may contain copper pipes with lead solder.** Use only water from the cold tap for drinking, cooking and especially making baby formula. Hot water is likely to contain higher levels of lead. These two actions are very important to the health of your family. They will probably be effective in reducing lead levels because most of the lead in household water usually comes from the plumbing in your house, not from the local water supply. Conserving water is still important. Rather than just running the water down the drain you could use the water for things such as watering your plants.*