## Royalwood Golf & RV Resort, Drinking Water System Annual Report for 2023

- This report covers from Jan. 01 2023 to Dec. 31 2023
- The owners are Ehrenholz Estates, Manager Dan
- Ehrenholz, Phone 604-823-4653 Ext.4
- The system operator is Dan Ehrenholz (operator cert. # 4678)
- A summary of the "Bacteriological Water Analysis" is attached.
- A summary of the arsenic monitoring test reports are attached
- A summary of the system operations (work done & improvements planned) are attached

## Royalwood uses both the Ultraviolet Light and Chlorine to disinfect the drinking water.

*Royalwood's system is a newer system and uses plastic pipes, but your RV may contain copper pipes with lead solder.* 

Anytime the water in a particular faucet has not been used for six hours or longer, "flush" your cold-water pipes by running the water until you notice a change in temperature. (This could take as little as five to thirty seconds if there has been recent heavy water use such as showering or toilet flushing. Otherwise, it could take two minutes or longer.) The more time water has been sitting in your home's pipes, the more lead it may contain.

Use only water from the cold-tap for drinking, cooking, and especially making baby formula. Hot water is likely to contain higher levels of lead.

The two actions recommended above are very important to the health of your family. They will probably be effective in reducing lead levels because most of the lead in household water usually comes from the plumbing in your house, not from the local water supply.

Conserving water is still important. Rather than just running the water down the drain you could use the water for things such as watering your plants.

## Page 2

## Sample Range Report

Fraser Health Authority

Facility Name:Royalwood Golf & RV Resort WSDate Range:Jan 1 2023 to Dec 31 2023 \$

Operator Dan Ehrenholz 41050 Trans Canada Hwy Chilliwack, BC V2R 4J1

Sampling Site	Date Collected	Total Coliform	E. Coli	Fecal Coliform
Royalwood Restaurant (new), 41050 Trans Canada	<u>a</u>			
<u>Hwy</u>	1-3-2023 11:00:00 AM	LT1	LT1	
	1-9-2023 12:30:00 PM	LT1	LT1	
	1-16-2023 11:00:00 AM	LT1	LT1	
	1-23-2023 10:30:00 AM	LT1	LT1	
	1-30-2023 11:00:00 AM	LT1	LT1	• 
	2-6-2023 11:00:00 AM	LT1	LT1	
	2-13-2023 11:00:00 AM	LT1	LT1	
	2-21-2023 11:00:00 AM	LT1	LT1	
	2-27-2023 11:00:00 AM	LT1	LT1	
	3-6-2023 11:00:00 AM	LT1	LT1	
	3-13-2023 12:00:00 PM	LT1	LT1	5
	3-20-2023 11:00:00 AM	LT1	LT1	
	3-28-2023 11:00:00 AM	LT1	LT1	
	4-3-2023 11:00:00 AM	LT1	LT1	
	4-11-2023 11:00:00 AM	LT1	LT1	
	4-17-2023 11:00:00 AM	LT1	LT1	
	4-24-2023 11:00:00 AM	LT1	LT1	
¢.	5-8-2023 12:00:00 PM	LT1	LT1	
	5-15-2023 11:00:00	LT1	LT1	

·Ľ					
and the second s					
.Ý					
	AM 5-23-2023 11:00:00 AM	LT1	LT1		
	5-29-2023 11:00:00 AM	LT1	LT1		
	6-5-2023 12:00:00	LT1	LT1		
•	6-12-2023 11:00:00 AM	LT1	LT1		
	6-19-2023 12:00:00 PM	LT1	LT1		
	6-26-2023 11:00:00 AM	LT1	LT1		
	7-4-2023 11:00:00 AM	LT1	LT1		
1	7-10-2023 11:00:00 AM	LT1	LT1		
	7-17-2023 11:00:00 AM	LT1	LT1		
	7-24-2023 11:00:00 AM	LT1	LT1		
	7-31-2023 11:00:00 AM	LT1	LT1		
	8-8-2023 11:00:00 AM	LT1	LT1		
	8-14-2023 12:00:00 PM	LT1	LT1	*	
	8-21-2023 11:00:00 AM	LT1	LT1		
	8-28-2023 11:00:00 AM	LT1	LT1		
	9-5-2023 11:00:00 AM	LT1	LT1		
	9-11-2023 11:00:00 AM	LT1	LT1		
	9-18-2023 11:00:00 AM	LT1	LT1		
	9-25-2023 11:00:00 AM	LT1	LT1		
	10-3-2023 11:00:00 AM	LT1	LT1	5	
	10-10-2023 11:00:00 AM	LT1	LT1		~
	10-16-2023 11:00:00 AM	LT1	LT1		
	10-23-2023 11:00:00 AM	LT1	LT1		
	10-30-2023 11:00:00 AM	LT1	LT1		
	11-6-2023 11:00:00 AM	LT1	LT1		
¢.	11-14-2023 11:00:00 AM	LT1	LT1		
	11-20-2023 11:00:00 AM	LT1	LT1		
			*		

coliform in last 30 c Total number of sa	days:			
Samples that conta Samples that conta Samples that conta Number of consec contain total colifor Number of sample	ain e. coli: 0 ain fecal coliform: 0 utive samples that 0 'm:		0.00% of 0.00% of 0.00% of	f total
Result Values:	E - estimated	L - less than	-	ater than
	Total Positive:	0	0	0
<u>Audit Royalwood R</u> <u>Park, 41050 Trans</u> <u>Canada Hwy</u>		<u>LT1</u>	<u>LT1</u>	
<u>AUDIT Clubhouse 1050 Trans Canad Hwy</u>		<u>LT1</u> 0	<u>LT1</u> 0	0
	Total Positive:	0	0	0
	10-10-2023 11:00:00 AM	<u>LT1</u>	LT1	0
	8-14-2023 12:00:00 PM	LT1	LT1	
	7-31-2023 11:00:00 AM	LT1	LT1	
	7-4-2023 11:00:00 AM	LT1	LT1	
	PM 6-5-2023 12:00:00 PM	LT1	LT1	
	AM 5-8-2023 12:00:00	LT1	LT1	
Royalwood RV Par Clubhouse, 41050 Trans Canada Hwy	<u>)</u> y 4-3-2023 11:00:00	LT1	LT1	
	Total Positive:	0	0	0
	12-18-2023 11:00:00 AM	<u>LT1</u>	<u>LT1</u>	
	AM 12-11-2023 11:00:00 AM	LT1	LT1	
	AM 12-4-2023 11:00:00	LT1	LT1	
	11-27-2023/11:00:00	LT1	LT1	

Comments:

Environmental Health Officer Jan 24 2024

FOR FURTHER INFORMATION PLEASE CALL: Jeniene Lutz (604) 870-7900

**QRWRT** indicates that the sample exceeded the 30 hour hold time. This could be due to courier issues or an incorrect date being recorded by the operator on the requisition forms. Water systems will still be given credit for the sample collected and a qualitative result is provided to Fraser Health. If there is bacteria detected, a separate email will be sent to the operator from Fraser Health.

**REJCT DELAY3** indicates that the sample has been rejected as it has been too long in transit. No results will be provided for this sample.